## EXECUTIVE SECRETARIAT ROUTING SLIP

TO:	-		ACTION	INFO	DATE	INITIAL	]
	1	DCI					1
		DDCI					1
		EXDIR					1
	4	D/ICS				<b> </b>	1
	5	DCI ,	1				1
	6	DDA	Viel	San	. T. T		
	7	DDO	· · · · · · · · · · · · · · · · · · ·	and the second			3
	8	DDS&I	Samuel		The State of the State of		
	<b>.9</b> :	Chm/NIC					
1974	10	GC .	10 100				4
	11:	IG.,				Alaga de alla de	
***	12	Compt	1769.55	manus of			
	13	D/Pers				The state of the s	-8-1
	14	D/OLL			i projek	i i i i i i i i i i i i i i i i i i i	-
	15	D/PAO		Sept Annual	The second secon	ا قرير دونهو مصنعت المواهد مستقدم دونهو الموارك و الرواد المواهدة	
	16	SA/IA		we did			
4.4	17-	AO/DCI	7 2 7 2 7				1
	18	C/IPD/OIS				· · · · · · · · · · · · · · · · · · ·	3.
	19						
	20		-::302	75122			
	21			1/8/3 %			
	22		12000	10000		1 1 1 1	
_	T	SUSPENSE	1 10 10 10 10	L. A. P. T. S. C.			ن شرور
				Date			
Remarks			8				
3 <b>537</b> (10	<b>3</b> 1)			্তি কৰিব কৰিব কৰিব কৰিব কৰিব কৰিব কৰিব কৰি	7/1		

Approved For Release 2008/08/22 : CIA-RDP86M00886R001800030015-7



## DEPARTMENT OF THE ARMY

## HEADQUARTERS US ARMY MILITARY DISTRICT OF WASHINGTON FORT LESLEY J. MCNAIR WASHINGTON, DC 20319

REPLY TO ATTENTION OF Executive Registry

84 - 1528

ANLOG

1 C APR 1984

SUBJECT: Military District of Washington Roadside Spot Check

Director , Central Intelligence Agency Longley, VA 22102

1. During a recent Roadside Spot Check conducted in the Military District of Washington on 26 March 1984, a vehicle assigned to your organization was inspected. A copy of DA Form 2404, Equipment Inspection and Maintenance Worksheet, listing deficiencies and/or shortcomings found during subject spot check is attached for your information.

2. POC: MSG Jojola, 274-7354.

1 Encl

as

CACHARD T. O'NEILL

Colonel, GS

Deputy Chief of Staff, Logistics

DCI EXEC REG

1-270

Approved For Release 2008/08/22 : CIA-RDP86M00886R001800030015-7

